

GALVANIZED FASTENERS

Full and half nuts – taped over size. Spring washers – form A

All spun galvanized to BS 7371

FULL NUT

Part No.	Size
2/GVF/001	M10
2/GVF/004	M12
2/GVF/007	M16
2/GVF/043	M20



FLAT WASHER FORM E

Part No.	Size
2/GVF/003	M10 x 21
2/GVF/006	M12 x 24
2/GVF/009	M16 x 30
2/GVF/041	M20 x 36



HALF NUT

Part No.	Size
2/GVF/030	M10
2/GVF/031	M12
2/GVF/032	M16



FLAT WASHER FORM F

Part No.	Size
2/GVF/003F	M10 x 30
2/GVF/006F	M12 x 35
2/GVF/009F	M16 x 50



SPRING WASHER

Part No.	Size
2/GVF/002	M10
2/GVF/005	M12
2/GVF/008	M16
2/GVF/042	M20



FLAT WASHER FORM G

Part No.	Size
2/GVF/035	M10 x 30
2/GVF/033	M12 x 35
2/GVF/040	M16 x 50



TAPER WASHER

Part No.	Size
2/GVF/010	M10
2/GVF/011	M12
2/GVF/012	M16



ROUND PACK WASHER

Part No.	Size
2/GVF/023	M10 x 8
2/GVF/024	M12 x 8
2/GVF/025	M16 x 8



SQUARE PACK WASHER

Part No.	Size	Thickness
2/GVF/014	M10	6
2/GVF/017	M12	6
2/GVF/015	M10	8
2/GVF/016	M10	10
2/GVF/020	M16	6
2/GVF/021	M16	8
2/GVF/022	M16	10

